

Benicia Refinery • Valero Refining Company - California

3400 East Second Street • Benicia, California 94510-1097 • Telephone (707) 745-7011 • Facsimile (707) 745-7339

TV Tracking #: 957 - B2626 (Semi-Annual)

TV Tracking #: 958 - A0901 (Semi-Annual)

TV Tracking #: 959 - B5574 (Semi-Annual)

1. D RECEIVED IN ENFORCEMENT: 07/30/2024 Sent via email

July 30, 2024

Refinery, Asphalt Plant & B5574 Monitoring Report for Jan 2024 – June 2024

Mr. Jeff Gove Director of Compliance and Enforcement Bay Area Air Quality Management District 375 Beale Street, Suite 600 San Francisco, CA 94105

Dear Mr. Gove:

Per Standard Condition I.F of Valero's Title V permits issued for the Fuels Refinery (B2626) and the Asphalt Plant (A0901) and Permit B5574, enclosed are the certified Semi-annual Monitoring Title V reports for all three facilities. Please note that the reporting convention for these reports is that deviations *discovered* during the calendar month are included along with any on-going events, regardless of when the event started.

The format and content of these reports is consistent with guidance provided by Mr. Steve Hill, BAAQMD Permit Evaluation Manager, in his letter dated January 8, 2004.

Please contact me at 707-745-7729 if you have any guestions or need further information.

Sincerely,

Carson Stacy

Associate Environmental Engineer

From 1/1/2024 to 6/30/2024

B2626 Val	lero Benicia Refinery			
Facility Address:		Mailin	ng Addre	ss:
3400 East Sec	cond Street	340	00 East S	econd Street
Benicia, CA 94	45101097	Bei	nicia, CA	945101097
,			,	
Contact: Ta	ryn Goodwin Title: M	lanager - Environmen	ntal Engin	eering Phone: (707) 745-7475
Title V deviations for the rep	porting period are summarized below:			
Event Starte 2/24/202	24 6:08 AM Stoppec 2/26/2024 5:00 PM	☐ Ongoing Event		
				May have resulted in a violation of:
Source Number: S77-Ta			Permit:	
Abatement Device:			AQMD:	8-5-304.4
Emission Point:			Other:	40 CFR 63.119(c)(2); 40 CFR 63.1063(b)(1)
	of hydrocarbon was approximately 35 gallons. During through a vacuum breaker. Based on the available in lbs. of hydrocarbon, including 0.6 lbs. of Benzene and Amendment 3/5/2024: On 2/24/24 at approximately	ng the investigation, it was information, the investign of 4 lbs. of H2S. Iy 6:08 AM, a conservation is underway to determined.	was deter gation tea tive quant termine h	d on the roof of Tank 1738, a floating roof tank. The amount mined that a vapor release was suspected to have occurred m estimated that the vapor release was approximately 3,297 ity of 83 gallons of refined hydrocarbon was identified on the ow the hydrocarbon material got onto the roof of Tank 1738.
Probable Cause:	During the investigation, it was determined that a va	apor release was suspe	cted to ha	ve occurred through a vacuum breaker.
	The tank was stilled so it could safely be cleaned. Bu	•		2/24/24 evening and clean up was completed on 2/26/24
Episode ID #:			NOV:	<u>57835</u>

Monday, July 29, 2024 Page 1 of 29

From 1/1/2024 to 6/30/2024

B2626 Va	alero Benicia Refinery			
Facility Address	:	Mailing	ng Address:	
3400 East Se	cond Street	3400	.00 East Second Street	
Benicia, CA	945101097	Beni	nicia, CA 945101097	
Contact: T	aryn Goodwin	Title: Manager - Environmenta	ntal Engineering Phone: (707) 745-7475	
Title V deviations for the r	reporting period are summarized below:			
Event Starte	024 5:25 AM Stoppec 2/24/2024	6:51 AM Ongoing Event		
			May have resulted in a violation of:	
Source Number: S77-	Tank, TK-1738	F	Permit:	
Abatement Device:		<i>F</i>	AQMD: 9-2-301	
Emission Point:			Other:	
1225 Event Description	: The H2S ground level monitor at GLM#1 in 6:00AM. The average during this period v		6 ppm limit, averaged over 3 consecutive minutes, from 5:25AM to	
	The H2S ground level monitor at GLM#1	recorded an excess above the 0.03 p	3 ppm limit, averaged over any 60 consecutive minutes, from 5:33A	<u>.M</u>
	to 6:51AM. The average during this perio	<u>d was 0.106 ppmv.</u>		
Probable Cause	: Material on roof of tank 1738 and vapor	release from TK-1738 vacuum break	aker.	
Corrective actions or preventative steps taken	Material was removed and cleaned. :			
Episode ID #	:		NOV:	

Monday, July 29, 2024 Page 2 of 29

From 1/1/2024 to 6/30/2024

B2626 \	/alero Benicia Refinery			
Facility Addres	ss:	Mailing A	ddress:	
3400 East S	Second Street	3400 E	ast Sec	ond Street
Benicia, CA	945101097	Benicia	a, CA 94	45101097
Contact:	Taryn Goodwin	Title: Manager - Environmental E	Enginee	ering Phone: (707) 745-7475
Title V deviations for the	reporting period are summarized below:			
Event Starte 2/27/2	2024 10:40 AM Stopper 2/27/2024	2:30 PM Ongoing Event		
			Ma	ay have resulted in a violation of:
Source Number: S77	7-Tank, TK-1738	Per	mit:	
Abatement Device:		AQI	MD: 8-!	5-322.5 ; 8-5-320.5
Emission Point:		Ot	her:	
1251 Event Description	on: <u>During a tank seal inspection by contract</u> regulation 8-5 criteria.	inspector, gaps were identified on the	e second	ary seal and the gauge pole slide plate greater than the
Probable Caus	se: <u>Normal wear</u>			
Corrective actions of preventative steps take	or <u>Inspection contractor repaired the gaps</u> en:	with tensioners. Rubber gasket and silic	cone we	ere used to close the slide plate gap.
Episode ID	#:	N	NOV: <u>57</u>	<u>836</u>

Monday, July 29, 2024 Page 3 of 29

From 1/1/2024 to 6/30/2024

B2626 Valero Benicia Refinery				
Facility Address: M	ailing Address:			
3400 East Second Street	3400 East Second Street			
Benicia, CA 945101097	Benicia, CA 945101097			
	,			
Contact: Taryn Goodwin Title: Manager - Environ	mental Engineering Phone: (707) 745-7475			
Title V deviations for the reporting period are summarized below:				
Event Start				
	May have resulted in a violation of:			
Source Number: S19-North Flare, ST-2103	Permit:			
Abatement Device:	AQMD:			
Emission Point: P3-North Flare Emission Point, P-3	Other: NESHAP 40 CFR 63.670 (e.); 40 CFR 60.103a(h)			
1292 Event Description: Amendment 3/27/2024: This is being filed as an excess only. These limits aren't currently in the Title V.				
	n zone measured below the minimum limit of 270 BTU/scf on 2/25/2024			
during the 2:15 and 3:45 15-minute periods. The North Flare (S-19) NE BTU/scf on 2/24/2024 during the 17:45, 19:00, and 22:15 15-Minute p				
BTO/SCI OII 2/24/2024 during the 17.45, 19:00, and 22:15 15-ivilitute p	erious.			
The North Flare (S-19) NHV of the combustion zone measured below the minimum limit of 270 BTU/scf on 2/24/2024 during the 17:45, 19:00,				
and 22:15 15-Minute periods.				
Additionally, the North Flags 2 have everyone U2C everyoded 1C2 representations	2/24/2024 in the 20:00 deals have an 2/25/2024 from cleak haves 2:00			
Additionally, the North Flare 3-hour average H2S exceeded 162 ppmv on 2/24/2024 in the 20:00 clock hour, on 2/25/2024 from clock hours 3:00-6:00, and on 2/26/2024 in the 7:00 clock hour. Since the flaring that occurred were process upset gases, the excess is exempt.				
	neutrea were process appearguses, the excess is exempt.			
Probable Cause: Process unit upsets				
Corrective actions or <u>Use of advanced controls to supplement with natural gas and the minimum preventative steps taken:</u>	mum amount of steam required.			

Monday, July 29, 2024 Page 4 of 29

From 1/1/2024 to 6/30/2024

B2626	Valero Benicia Refinery		
Facility	Address:	Mailing Addre	ess:
3400	East Second Street	3400 East	Second Street
Beni	cia, CA 945101097	Benicia, CA	A 945101097
Со	ntact: Taryn Goodwin	Title: Manager - Environmental Engi	neering Phone: (707) 745-7475
Title V deviations	for the reporting period are summarized below:		
Epis	sode ID #: 200211;200211	NOV:	62813
Event Starte	1/1/2024 12:00 AM Stopped 1/5/2024	4 1:00 PM Ongoing Event	
Carrage Niversity	C4 Asid Cas Burnary F 4204A C2 Asid Cas Bu	Dit	May have resulted in a violation of:
	per: S1-Acid Gas Burner, F-1301A; S2-Acid Gas Bu	<u>'</u>	
Emission Po	ice: A56-Tail Gas Cleanup Unit on SGU A/B Trainsint:		40 CFR Part 60 Appendix F 5.1
1295 Event De	1/5/2024.	CEMS was not audited by CGA, RAA, or RATA	in the 4th quarter of 2023. An RAA was conducted on
	The Flexsorb TRS CEMS was not audite	ed by CGA, RAA, or RATA in the 4th quarter of	<u>2023.</u>
Probab	ole Cause: Contracting company hired to conduct	t testing was not able to complete testing bef	ore the end of the quarter.
Corrective a preventative ste	ctions or <u>The test was completed on 1/5/2024.</u> eps taken:		
Epis	sode ID #:	NOV:	<u>62803</u>

Monday, July 29, 2024 Page 5 of 29

From 1/1/2024 to 6/30/2024

B2626 Valero Benicia Refinery	
Facility Address: N	Nailing Address:
3400 East Second Street	3400 East Second Street
Benicia, CA 945101097	Benicia, CA 945101097
Contact: Taryn Goodwin Title: Manager - Enviror	nmental Engineering Phone: (707) 745-7475
Title V deviations for the reporting period are summarized below:	
Event Start	ut .
	May have resulted in a violation of:
Source Number: S5-FCCU Regenerator, R-702; S6-Coker Burner, R-902; S1059-CO Furnace F-	Permit: 24245.19
105; S1060-CO Furnace F-106	
Abatement Device: A1059-Flue Gas Scrubber SCR	AQMD: 6-1-301; 6-1-302; SIP 6-301; SIP 6-302; 6-1-310; SIP 6-310
Emission Point: P1059-FGS Stack ST-5601	Other: 40CFR Part 60.102(a)(2); 40 CFR Part 63.1564(a) (1)
1297 Event Description: Amendment 4/17/2024: The parametric variable "delta P across the A	agglo Filtering Module (AFM)" recovered to above the hourly minimum limit
of >19 inches of H2O on 4/11/2024. The minimum limit could not be	
On 2/23/2024 the Flue Gas Scrubber (FGS) parametric variable "delta minimum limit of >19 inches of H20.	P across the Agglo Filtering Module (AFM)" dropped below the hourly
Probable Cause: The Coker and the FCCU were intermittently shut down. It is not poss	· ·
normal rates. This hourly parametric limit was established during a per running at normal rates.	rnormance test conducted when both the FCCO and Coker units were
Corrective actions or It is not possible to meet this hourly parametric limit when not running preventative steps taken:	ng both units at normal rates
Episode ID #: <u>200210</u>	NOV: <u>62162</u>

Monday, July 29, 2024 Page 6 of 29

From 1/1/2024 to 6/30/2024

B2626 Valero Ben	cia Refinery
Facility Address:	Mailing Address:
3400 East Second Street	3400 East Second Street
Benicia, CA 945101097	Benicia, CA 945101097
200.0, 0 22.0202	201110101, 01.1 01.0202007
Contact: Taryn Goodw	n Title: Manager - Environmental Engineering Phone: (707) 745-7475
Title V deviations for the reporting perio	d are summarized below:
Event Start: 11/9/2023 4:00 P	M Stoppec 12/1/2023 4:00 PM □ Ongoing Event
	May have resulted in a violation of:
Source Number: REFFUG-Benicia R	·
Abatement Device:	AQMD: 8-18
Emission Point:	Other:
audit of the component	2/14/24: 4Q-23 refinery fugitives deviation report includes: valves and connectors previously not documented. After conducting an LDAR component tagging in the hydrogen system, we have added 703 valves and 3211 connectors to the LDAR program. The have an add date of 12/1/2023. All newly added components have been monitored. November 9, 2023 is start date of when emponents were initially identified/discovered during the audit. December 1, 2023 is the end date when the identification process red.
After condu program. Th	ry fugitives deviation report includes: valves and connectors previously not documented. Sting an audit of the LDAR component tagging in the hydrogen system, we have added 703 valves and 3211 connectors to the LDAR e components have an add date of 12/1/2023. All newly added have been monitored.
	Refinery has over 360,000 components in its database. A healthy fugitive emissions program will self-audit to identify single items or may not be in compliance. By identifying these outliers, program improvements can be achieved.
	iting of refinery fugitives program. Identification of potential non-compliant components during routine monitoring. Special focused provement projects are conducted to improve units that are identified as needing improvement.

Monday, July 29, 2024 Page 7 of 29

From 1/1/2024 to 6/30/2024

B2626 Valero Benicia Refinery

Facility Address: Mailing Address:

3400 East Second Street

Benicia, CA 945101097

Benicia, CA 945101097

Contact: Taryn Goodwin Title: Manager - Environmental Engineering Phone: (707) 745-7475

Title V deviations for the reporting period are summarized below:

Required components were inspected after discovery.

Episode ID #: NOV: 62164

Monday, July 29, 2024 Page 8 of 29

From 1/1/2024 to 6/30/2024

B2626 Valero Benicia Refinery	
Facility Address: Ma	ailing Address:
3400 East Second Street	3400 East Second Street
Benicia, CA 945101097	Benicia, CA 945101097
Contact: Taryn Goodwin Title: Manager - Environr	mental Engineering Phone: (707) 745-7475
Title V deviations for the reporting period are summarized below:	
Event Start	
	May have resulted in a violation of:
Source Number: S1030-Combustion Turbine Generator, GT-4901; S1031-Heat Recovery Steam Generator, SG-4901	Permit:
Abatement Device:	AQMD: 1-522.4
Emission Point:	Other:
after a period of inoperation greater than 24 continuous hours.	24 3:04 pm. The Inop is being reported beyond the following business day
was re-calibrated and passed 1/19/2024 3:04 pm	on. Analyzer became inoperative >24hrs on 1/16/2024 at 6:31 AM. Analyzer
Probable Cause: While performing maintenance on the cogen fuel gas analyzer on 1/13, concentration on the analyzer validation report. Due to the mislabel, Vamonitor until 1/19/2024.	· · · · · · · · · · · · · · · · · · ·
Corrective actions or <u>Valero personel adjusted the span to the correct values, re-cal and re-values taken:</u>	al cogen TRS/H2S monitor.
Episode ID #: 200115	NOV: 62806

Monday, July 29, 2024 Page 9 of 29

From 1/1/2024 to 6/30/2024

B2626	Valero Benicia Refinery	
Facility	Address:	lailing Address:
3400	0 East Second Street	3400 East Second Street
Beni	icia, CA 945101097	Benicia, CA 945101097
Co	ontact: Taryn Goodwin Title: Manager - Enviror	mental Engineering Phone: (707) 745-7475
Title V deviations	s for the reporting period are summarized below:	
Event Starte	2/4/2024 10:00 PM Stoppec <u>2/5/2024 12:00 AM</u> ☐ Ongoing Ever	
		May have resulted in a violation of:
Source Num	ber: S1030-Combustion Turbine Generator, GT-4901; S1031-Heat Recovery Steal Generator, SG-4901	n Permit: 19177.19b
Abatement Dev	vice:	AQMD:
Emission Po	pint: P60-Cogen Stack GT/SG-4901	Other:
1301 Event De	escription: GT-4901/SG-4901 exceeded the 2.5 ppm NOx 3-hr avg limit on 2/4/2	024 22:00 - 23:00. The average concentration during the excess was 4.4 ppm.
Probab	ble Cause: Cogen start-up.	
Corrective a preventative ste	actions or SG-4901 firing was adjusted and ammonia injection was lined out to eps taken:	oring NOx emissions back within limits.
Epi	sode ID #: <u>200154</u>	NOV:

Monday, July 29, 2024 Page 10 of 29

From 1/1/2024 to 6/30/2024

82626 Valero Benicia Refinery	
Facility Address:	Mailing Address:
3400 East Second Street	3400 East Second Street
Benicia, CA 945101097	Benicia, CA 945101097
Contact: Taryn Goodwin	Title: Manager - Environmental Engineering Phone: (707) 745-7475
Title V deviations for the reporting period are summarized below:	
Event Start	3:30 PM Ongoing Event
	May have resulted in a violation of:
Source Number:	Permit:
Abatement Device:	AQMD: 1-441
Emission Point:	Other:
	efinery received an NOV (63216) from BAAQMD. The NOV was issued for failure to respond to Reg. 1-441
Information Request. Valero does not a	agree with this NOV and has scheduled a meeting with BAAQMD to discuss.
· · · · · · · · · · · · · · · · · · ·	efinery received an NOV (63216) from BAAQMD. The NOV was issued for failure to respond to Reg. 1-441
	agree with this NOV and has scheduled a meeting with BAAQMD to discuss.
•	efinery received an NOV (63216) from BAAQMD. The NOV was issued for failure to respond to Reg. 1-441 agree with this NOV and has scheduled a meeting with BAAQMD to discuss.
Episode ID #:	NOV: 63216

Monday, July 29, 2024 Page 11 of 29

From 1/1/2024 to 6/30/2024

B2626	valero Benicia Refinery			
Facility	Address:	Maili	ng Addre	ess:
340	0 East Second Street	34	100 East S	Second Street
Ben	icia, CA 945101097	Ве	enicia, CA	A 945101097
Co	ontact: Taryn Goodwin	Title: Manager - Environme	ntal Engir	neering Phone: (707) 745-7475
Title V deviation	s for the reporting period are summarized below:			
Event Starte	2/26/2024 11:45 AM Stopper 2/26/202	4 12:00 PM Ongoing Event		
				May have resulted in a violation of:
Source Num	ser: S82-Tank, TK-1754		Permit:	
Abatement De	vice:		AQMD:	8-5-322.5
Emission P	oint:		Other:	
1304 Event Do	escription: <u>During a tank seal inspection by contrological criteria.</u>	ract inspector and BAAQMD on TK-17	754, contra	ract inspector identified a gap greater than regulation 8-5
Proba	ble Cause: Normal wear			
Corrective preventative st	actions or <u>Inspection contractor closed the gaps</u> eps taken:	by adjusting the hardware and rech	ecked.	
Ер	isode ID #:		NOV:	

Monday, July 29, 2024 Page 12 of 29

From 1/1/2024 to 6/30/2024

B2626 Valero Benicia Refinery	
Facility Address:	Mailing Address:
3400 East Second Street	3400 East Second Street
Benicia, CA 945101097	Benicia, CA 945101097
Contact: Taryn Goodwin Title	: Manager - Environmental Engineering Phone: (707) 745-7475
Title V deviations for the reporting period are summarized below:	
Event Startc <u>2/26/2024 12:00 AM</u> Stoppec <u>2/26/2024</u> 8:00	AM Ongoing Event
	May have resulted in a violation of:
Source Number: S37-Waste Heat Boiler, SG-702	Permit: 16386.1
Abatement Device:	AQMD:
Emission Point: P21/P22-SG-702 West/East Stack, P-21/P-22	Other:
1305 Event Description: On 2/26/2024, SG-702 exceeded the rolling 3-ho hour average concentration for the hours in exceeding the second	our NOx average permit limit of 9ppm at 12:00 AM and from 6:00 AM to 8:00 AM. The mean 3-eedance of the limit was 11.22ppm.
Probable Cause: SG-702 and GT-702 shut down due to C-702 trip	offline. Excess took place shortly after fuel gas introduced to SG-702 for start-up.
Corrective actions or <u>Unit was shut down.</u> preventative steps taken:	
Episode ID #: RCA200217	NOV:

Monday, July 29, 2024 Page 13 of 29

From 1/1/2024 to 6/30/2024

B2626	Valero Benicia Refinery					
Facility A	Address:	Mail	ing Addre	ess:		
3400	East Second Street	3	400 East \$	Second Stree	t	
Benic	ia, CA 945101097	В	enicia, CA	945101097		
Con	ntact: Taryn Goodwin	Title: Manager - Environme	ntal Engir	neering	Phone: (707) 745-7475	
Title V deviations j	for the reporting period are summarized below:					
Event Starte	2/23/2024 10:00 PM Stoppec 2/24/2024	2:00 PM Ongoing Event				
			_	May have res	sulted in a violation of:	
Source Number	er: S220-Hot Oil Furnace, F-4460		Permit:	10574.24		
Abatement Device			AQMD:			_
Emission Poi	nt: P46-CFP Hot Oil Furnace Stack, P-46		Other:			_
1306 Event Des	cription: During the clock hours 22:00 2/23/202- concentration during the excess was 15		d the rollin	g 8-hour CO a	verage permit limit of 28 ppm. The average	
Probabl	e Cause: Process unit upsets due to C-702 trip.					
Corrective ac preventative step	tions or <u>F-4460 stabilized after process unit ups</u> os taken:	ets were resolved.				
Episo	ode ID #: RCA200213		NOV:			

Monday, July 29, 2024 Page 14 of 29

From 1/1/2024 to 6/30/2024

B2626 Va	alero Benicia Refinery			
Facility Address	s:	Mailin	g Addre	ss:
3400 East Se	econd Street	340	00 East S	Second Street
Benicia, CA	945101097	Bei	nicia, CA	945101097
Contact: T	Faryn Goodwin	Title: Manager - Environmen	tal Engin	neering Phone: (707) 745-7475
Title V deviations for the r	reporting period are summarized below:			
Event Starte 3/2/20	024 10:50 PM Stopper 3/3/2024	10:50 AM Ongoing Event		
			,	May have resulted in a violation of:
Source Number:			Permit:	Condition 24198, Part 17
Abatement Device:			AQMD:	6-1-302; SIP 6-302
Emission Point: P69-	-FCCU/CKR Dumpstack		Other:	
1307 Event Description	: On 3/2/2024, the FCCU water seal at th The seal was reestablished 3/3/2024 at		-	sedures in order to isolate the FCCU unit in a safe manner. Suant to Condition 24198, Part 17.
Probable Cause	e: The water seal was drained per shutdov	wn procedures.		
Corrective actions or preventative steps taken	The water seal was reestablished as soc	on as possible.		
Episode ID #	c		NOV:	

Monday, July 29, 2024 Page 15 of 29

From 1/1/2024 to 6/30/2024

B2626	Valero Benicia Refinery					
Facility Address:		Mailing Address:				
340	00 East Second Street	3400 East Second Street				
Ber	nicia, CA 945101097	Benicia, CA 945101097				
С	ontact: Taryn Goodwin	Title: Manager - Environmental Engineering Phone: (707) 745-7475				
Title V deviation	ns for the reporting period are summarized below:					
Event Starte	3/1/2024 4:00 PM Stoppec 3/1/2024	4:00 PM Ongoing Event				
		May have resulted in a violation of:				
Source Nun	nber: NONE FPU site-Refinery (site)	Permit:				
Abatement De	evice:	AQMD: Reg. 1-301				
Emission P	Point:	Other:				
1308 Event D	Description: On March 1, 2024, Valero Benicia Refi	nery received an NOV (62805) from the BAAQMD. The NOV was for confirmed complaints from 2/24/2024				
Proba	able Cause: On March 1, 2024, Valero Benicia Refi	nery received an NOV (62805) from the BAAQMD. The NOV was for confirmed complaints from 2/24/2024				
Corrective preventative st		nery received an NOV (62805) from the BAAQMD. The NOV was for confirmed complaints from 2/24/2024				
Ep	pisode ID #:	NOV: <u>62805</u>				

Monday, July 29, 2024 Page 16 of 29

From 1/1/2024 to 6/30/2024

B2626	Valero Benicia Refinery				
Facility Add	lress:	Maili	ing Addre	ess:	
3400 Ea	st Second Street	34	400 East 9	Second Street	
Benicia,	CA 945101097	В	enicia, CA	945101097	
Conta	ct: Taryn Goodwin	Title: Manager - Environme	ntal Engir	neering	Phone: (707) 745-7475
Title V deviations for	the reporting period are summarized below:				
Event Start 3,	/8/2024 3:46 PM Stoppec 3/8/2024	4:41 PM Ongoing Event			
			_	May have resulte	ed in a violation of:
Source Number:	S1010-Hydrogen Production Facilities		Permit:	27609 Part 1	
Abatement Device:			AQMD:	Reg. 8-2-301	
Emission Point:	P1010-ST-302		Other:		
1310 Event Descrip	otion: On 3/8/24, P017 valve opened from 3:4 302) to atmosphere. A project has been				otal carbon was released from vent P1010 (ST-shutdown and process upsets.
Probable C	ause: 1900# hydrogen grid experinced grid in:	stabilty.			
Corrective actio preventative steps t	ns or <u>Hydrogen Grid pressure was stabilized</u> aken:				
Episode	e ID #:		NOV:		

Monday, July 29, 2024 Page 17 of 29

From 1/1/2024 to 6/30/2024

B2626	Valero Benicia Refinery		
Facility	Address:	Mailing Addre	ess:
340	0 East Second Street	3400 East 5	Second Street
Ben	icia, CA 945101097	Benicia, CA	945101097
Co	ontact: Taryn Goodwin	Title: Manager - Environmental Engir	neering Phone: (707) 745-7475
Title V deviation	s for the reporting period are summarized below:		
Event Starte	3/13/2024 4:00 PM Stopped 3/13/2024	4:00 PM Ongoing Event	
			May have resulted in a violation of:
Source Num	ber: S1030-Combustion Turbine Generator, GT-49 Generator, SG-4901	901; S1031-Heat Recovery Steam Permit:	
Abatement De	vice:	AQMD:	
Emission P	oint:	Other:	40CFR 60.13 (e)
1312 Event De	escription: On March 13, 2024, Valero Benicia Re Cogen on 12/27/23.	finery received an NOV (62807) for failure to o	continuously operate the H2S CEMS monitoring system at
Proba	ble Cause: On March 13, 2024, Valero Benicia Ref Cogen on 12/27/23.	inery received an NOV (62807) for failure to c	continuously operate the H2S CEMS monitoring system at
	actions or On March 13, 2024, Valero Benicia Refeps taken: Cogen on 12/27/23.	inery received an NOV (62807) for failure to c	continuously operate the H2S CEMS monitoring system at
Fn	isode ID #·	NOV.	62807

Monday, July 29, 2024 Page 18 of 29

From 1/1/2024 to 6/30/2024

B2626	Valero Benicia Refinery		
Facility A	Address:	Mailing Addre	ess:
3400	East Second Street	3400 East	Second Street
Benio	cia, CA 945101097	Benicia, CA	A 945101097
Cor	ntact: Taryn Goodwin	Title: Manager - Environmental Engi	neering Phone: (707) 745-7475
Title V deviations	for the reporting period are summarized below:		
Event Starte	3/18/2024 4:34 PM Stoppec 3/21/2024	2:45 AM Ongoing Event	
			May have resulted in a violation of:
Source Numb	per:	Permit:	Condition 24198, Part 17
Abatement Devi	ice:	AQMD:	6-1-302; SIP 6-302
Emission Poi	int: P69-FCCU/CKR Dumpstack	Other:	
1313 Event Des	· ·	the dumpstack (P-69) was drained per startu 21/2024 at 2:45 am. This excess is being subm	p procedures in order to remove the FCCU unit blind for nitted pursuant to Condition 24198, Part 17.
Probab	le Cause: The water seal was drained per startup	procedures.	
Corrective ac preventative step	ctions or <u>The water seal was reestablished as so</u> ps taken:	on as possible.	
Epis	ode ID #: <u>200252</u>	NOV:	

Monday, July 29, 2024 Page 19 of 29

From 1/1/2024 to 6/30/2024

B2626	Valero Benicia Refinery				
Facility Address: Mailin			ng Address:		
3400 East Second Street 34			400 East S	econd Street	
Benicia, C	A 945101097	Be	enicia, CA	945101097	
Contact	: Taryn Goodwin	Title: Manager - Environme	ntal Engin	eering Phone: (707) 745-7475	
Title V deviations for th	ne reporting period are summarized below:				
Event Starte 3/24,	/2024 9:00 PM Stoppec 3/24/2024	9:15 PM Ongoing Event			
				May have resulted in a violation of:	
Source Number: S2	19-North Flare, ST-2103		Permit:		
Abatement Device:			AQMD:		
Emission Point: P	3-North Flare Emission Point, P-3		Other:	NESHAP 40 CFR 63.670 (e.); 40 CFR 60.103a(h)	
1314 Event Descripti	ion: Amendment (3/29/24): This is being file	ed as an excess only. These limits ar	re not curre	ently in the Title V.	
	The North Flare (S-19) NHV of the combined block.	bustion zone measured below the r	<u>minimum li</u>	mit of 270 BTU/scf on 3/24/2024 during the 21:00 15-minute	
Probable Cau	use: Imbalance of steam and flare flow.				
Corrective actions preventative steps tak	or <u>Flaring stopped.</u> sen:				
Episode II	D#: <u>200256</u>		NOV:		

Monday, July 29, 2024 Page 20 of 29

From 1/1/2024 to 6/30/2024

B2626 Valero Benicia Refinery	
Facility Address:	Mailing Address:
3400 East Second Street	3400 East Second Street
Benicia, CA 945101097	Benicia, CA 945101097
Contact: Taryn Goodwin	Title: Manager - Environmental Engineering Phone: (707) 745-7475
Title V deviations for the reporting period are summarized below:	
Event Start 3/31/2024 12:00 AM Stopped 3/31/2024	12:00 AM Ongoing Event
	May have resulted in a violation of:
Source Number: S1059-CO Furnace F-105; S1060-CO Furnace F-	106 Permit: 20820.63, 20820.68
Abatement Device: A1047-Flue Gas Scrubber (Belco & Cansolv); A2	.059-Flue Gas Scrubber SCR AQMD:
Emission Point: P1059-FGS Stack ST-5601	Other:
1316 Event Description: The 1 day average CO limit of 100 ppm v	vas exceeded on 3/30/2024. The average concentration during this period was 110 ppm.
Probable Cause: In process of shutting down unit.	
Corrective actions or <u>Adjustments were made at Pipestill furn</u> preventative steps taken:	aces to lower the CO.
Episode ID #:	NOV:

Monday, July 29, 2024 Page 21 of 29

From 1/1/2024 to 6/30/2024

B2626 Va	alero Benicia Refinery			
Facility Address	::	Maili	ng Addre	SS:
3400 East Se	econd Street	34	400 East S	econd Street
Benicia, CA	945101097	Ве	enicia, CA	945101097
Contact: T	aryn Goodwin	Title: Manager - Environme	ntal Engir	eering Phone: (707) 745-7475
Title V deviations for the r	reporting period are summarized below:			
Event Starte 3/27/20	024 5:30 AM Stoppec 3/28/2024	1 11:45 AM Ongoing Event		
				May have resulted in a violation of:
Source Number: S19-	North Flare, ST-2103		Permit:	
Abatement Device:			AQMD:	
Emission Point: P3-N	North Flare Emission Point, P-3		Other:	NESHAP 40 CFR 63.670 (e.); 40 CFR 60.103a(h)
1318 Event Description	: Amendment 4/2/2024: The North Flar	e (S-19) NHV of the combustion zon	e measure	d below the minimum limit of 270 BTU/scf on 3/27/2024
·				1:00, 11:15, 11:30, and 11:45 15-minute blocks. The average
	NHV for these events are 190 BTU/scf.	This is being filed as an excess only	. These lim	its are not currently in the Title V.
	`	2024 during the 23:00, 23:15, 23:30	, and 23:45	mit of 270 BTU/scf on 3/27/2024 during the 05:30, 23:30 and 5 15-minute blocks. The average NHV for these events are 190 e V.
Probable Cause	: Steam not balanced with flare flow.			
Corrective actions or preventative steps taken				
Episode ID #			NOV:	

Monday, July 29, 2024 Page 22 of 29

From 1/1/2024 to 6/30/2024

B2626	Valero Benicia Refinery					
Facility Address:		Mailing Address:				
3400 E	East Second Street	3	400 East 9	Second Street		
Benicia	a, CA 945101097	В	enicia, CA	A 945101097		
Cont	tact: Taryn Goodwin	Title: Manager - Environme	ental Engir	neering Phone: (707) 745-7475		
Title V deviations fo	or the reporting period are summarized below:					
Event Starte 3	3/29/2024 1:16 PM Stoppec 3/29/2024	11:55 PM Ongoing Event				
			_	May have resulted in a violation of:		
Source Numbe	r: S1010-Hydrogen Production Facilities		Permit:	27609 Part 1		
Abatement Device	e:		AQMD:	Reg 8-2-301		
Emission Poin	t: P1010-ST-302		Other:			
1319 Event Desc	·			roximately 15.6 lbs. of Total Carbon was released from vent om this vent during startup, shutdown and process upsets.		
Probable	Cause: 1900# Hydrogen grid experienced grid	instability.				
Corrective act preventative steps	ions or <u>Hydrogen grid pressure stabilized.</u> s taken:					
Episo	de ID #:		NOV:			

Monday, July 29, 2024 Page 23 of 29

From 1/1/2024 to 6/30/2024

Mailing	g Address:
340	00 East Second Street
Ben	nicia, CA 945101097
Title: Manager - Environment	tal Engineering Phone: (707) 745-7475
4:00 PM Ongoing Event	May have resulted in a violation of:
eat Boiler, SG-702	Permit: 16386.1
•	AQMD:
	Other:
rolling 3-hour NOx average permit 0.20 ppm.	limit of 9ppm at 4:00 PM. The mean 3-hour average concentration for
	NOV:
	340 Ber Title: Manager - Environment 4:00 PM

Monday, July 29, 2024 Page 24 of 29

From 1/1/2024 to 6/30/2024

B2626	Valero Benicia Refinery		
Facility	y Address:	Mailing Ad	dress:
340	00 East Second Street	3400 Ea	st Second Street
Ber	nicia, CA 945101097	Benicia,	CA 945101097
C	Contact: Taryn Goodwin	Title: Manager - Environmental E	ngineering Phone: (707) 745-7475
Title V deviation	ns for the reporting period are summarized below:		
Event Starte	3/31/2024 8:34 PM Stoppec 4/2/2024	8:41 AM Ongoing Event	
Event Startt	3/31/2024 6.34 FIVI Stoppet 4/2/2024	Oligonia Event	May have resulted in a violation of:
Source Nun	mhar	Dorn	nit: Condition 24198, Part 17
Abatement De			ID: 6-1-302; SIP 6-302; 1-522.7
		Oth	
EIIIISSIOII P	Point: P69-FCCU/CKR Dumpstack	Oth	er.
1321 Event D	Description: Amendment 4/8/2024: On 3/31/2024,	the FCCU water seal at the dumpstack (P-	69) was drained per shutdown procedures in order to remove the
		-	his excess is being submitted pursuant to Condition 24198, Part
	17. Additionally, the excess and deviati	on is being reported late.	
	On 3/31/2024, the ECCII water seal at t	the dumnstack (P-60) was drained per shu	tdown procedures in order to remove the FCCU unit blind for
		• • • • • • • • • • • • • • • • • • • •	submitted pursuant to Condition 24198, Part 17.
Dunha		•	Marineted parsault to condition 2 1230, 1 die 171
	able Cause: The water seal was drained per shutdo	.	
	actions or <u>The water seal was reestablished as soo</u>	on as possible.	
preventative s			
Ep	oisode ID #:	NO	OV:

Monday, July 29, 2024 Page 25 of 29

From 1/1/2024 to 6/30/2024

B2626 Valero Benicia Refinery	
Facility Address: Ma	ailing Address:
3400 East Second Street	3400 East Second Street
Benicia, CA 945101097	Benicia, CA 945101097
Contact: Taryn Goodwin Title: Manager - Environn	mental Engineering Phone: (707) 745-7475
Title V deviations for the reporting period are summarized below:	
Event Starte 4/6/2024 4:40 PM Stoppec 4/9/2024 12:20 AM Ongoing Event	
	May have resulted in a violation of:
Source Number:	Permit: Condition 24198, Part 17
Abatement Device:	AQMD: 6-1-302; SIP 6-302
Emission Point: P69-FCCU/CKR Dumpstack	Other:
1322 Event Description: Amendment On 4/6/2024, the FCCU water seal at the dumpstack (P-69 at 12:20 am. This excess is being submitted pursuant to Condition 2419	98, Part 17.
On 4/6/2024, the FCCU water seal at the dumpstack (P-69) was drained	d per startup procedures.
Probable Cause: The Water seal was drained per startup procedures.	
Corrective actions or <u>The water seal was reestablished as soon as possible.</u> preventative steps taken:	
Episode ID #: 200270	NOV:

Monday, July 29, 2024 Page 26 of 29

From 1/1/2024 to 6/30/2024

Valero Benicia Refinery	
Facility Address:	Mailing Address:
3400 East Second Street	3400 East Second Street
Benicia, CA 945101097	Benicia, CA 945101097
Contact: Taryn Goodwin	Title: Manager - Environmental Engineering Phone: (707) 745-7475
Title V deviations for the reporting period are summarized below:	
Event Start: 4/10/2024 4:00 AM Stoppe: 4/10/2024	4:15 AM Ongoing Event
	May have resulted in a violation of:
Source Number: S19-North Flare, ST-2103	Permit:
Abatement Device:	AQMD:
Emission Point: P3-North Flare Emission Point, P-3	Other: NESHAP 40 CFR 63.670 (e.); 40 CFR 60.103a(h)
	stion zone measured below the minimum limit of 270 BTU/scf on 4/10/2024 during the 4:00 15-minute. These limits are not currently in the Title V.
Probable Cause: Steam not balanced with flare flow.	
Corrective actions or Flaring stopped. preventative steps taken:	
Episode ID #:	NOV:

Monday, July 29, 2024 Page 27 of 29

From 1/1/2024 to 6/30/2024

B2626	Valero Benicia Refinery				
Facility	Address:	Mailing	g Addres	ss:	
3400	East Second Street	340	0 East S	econd Stree	et
Beni	cia, CA 945101097	Ben	icia, CA	945101097	7
Co	ntact: Taryn Goodwin	Title: Manager - Environment	al Engin	eering	Phone: (707) 745-7475
Title V deviations	s for the reporting period are summarized below:				
Event Starte	5/1/2024 9:29 AM Stoppec 5/8/202	4 12:50 PM Ongoing Event			
			ı	May have re	sulted in a violation of:
Source Numb	oer: unassigned-Tank, Refrigerated Butane Tank,	, TK-1726	Permit:		
Abatement Dev	rice:		AQMD:	8-5-306.2	
Emission Po	int:		Other:		
1325 Event De	scription: PV Vent (17109) located on TK-1726 e replacement efforts are complete and	exceeded 500ppm emission standard du I confirmed to be below the emission s	_		utine fugitive emissions inspection. Valve
Probab	ole Cause: PV Vent not Gas Tight				
	ections or <u>SV-17109 was swapped out on 5/8/24</u> eps taken: <u>LDAR# 181946</u>	1 with SV-17160SP			
Epis	sode ID #:		NOV:		

Monday, July 29, 2024 Page 28 of 29

From 1/1/2024 to 6/30/2024

B2626	Valero Benicia Ref	inery			
Facilit	y Address:		Mailing Address:		
	00 East Second Street nicia, CA 945101097		3400 East Second Benicia, CA 9451		
C	Contact: Taryn Goodwin	Title: Ma	anager - Environmental Engineerin	g Phone: (707) 74	5-7475
Title V deviation	ns for the reporting period are sun	nmarized below:			
<u>Certification</u>	<u>Statement</u>				
reasonable inc	penalty of law that based on the i uiry, the statements and informat nd other materials are true, accur	ion in this document and in all	after		
× Ja	uren K. Brind	Lauren Bird	Vice President and Gen	eral Manager	
Signature of	Responsible Official	Print Name	Title		Date

From 1/1/2024 to 6/30/2024

A0901 Valero Benicia Asphalt P	lant
Facility Address:	Mailing Address:
3001 Park Road	3001 Park Road
Benicia, CA 94510	Benicia, CA 94510
Contact: Taryn Goodwin	Title: Manager - Environmental Engineering Phone: (707) 745-7475
Title V deviations for the reporting period are summarized	below:
Event Start 3/11/2024 12:46 AM Stopped 3/	
	May have resulted in a violation of:
Source Number: S24-Hot Oil Heater, H-3 (natural gas)	
Abatement Device:	AQMD:
Emission Point:	Other:
•	or recovery incinerator, H-4603 (S24) tripped offline. The temperature dropped below the minimum 1115 degrees :46 - 01:06. The average temperature during this time was 780 degrees Fahrenheit.
Probable Cause: False high oil temperature.	
Corrective actions or <u>Transmitter repair.</u> preventative steps taken:	
Episode ID #: 200240	NOV:

Wednesday, July 24, 2024 Page 1 of 2

From 1/1/2024 to 6/30/2024

A0901	Valero Benicia As	phalt Plant		
Facility	y Address:		Mailing Address:	
300	01 Park Road		3001 Park Road	
Ber	nicia, CA 94510			
C	ontact: Taryn Goodwin	Title: Ma	anager - Environmental Engineering	Phone: (707) 745-7475
Title V deviation	ns for the reporting period are su	ımmarized below:		
<u>Certification</u>	<u>Statement</u>			
reasonable inq		e information and belief formed a ation in this document and in all irate, and complete.		
x Jaw	ruy K. bud	Lauren Bird	Vice President and General M	
Signature of	Posnonsible Official	Drint Nama	Titlo	Date

From 1/1/2024 to 6/30/2024

R	557	Δ	Nustar	Ogisti	CE
Ŀ	331		1403601	robise	100

Facility Address:

3400 East Second Street Benicia, CA 94510

Contact: Taryn Goodwin

Mailing Address:

3400 East Second Street Benicia, CA 945101097

Title: Manager - Environmental Engineering

Phone: (707) 745-7475

Title V deviations for the reporting period are summarized below:

No deviation for this time period.

Certification Statement

I certify under penalty of law that based on the information and belief formed after reasonable inquiry, the statements and information in this document and in all attachments and other materials are true, accurate, and complete.

x Jaury K. Bry	Lauren Bird	Vice President and General Manager		
Signature of Responsible Official	Print Name	Title	Date	

From 1/1/2024 to 6/30/2024

B2626 Valero Beni	nicia Refinery
Facility Address: 3400 East Second Street Benicia, CA 945101097 Contact: Taryn Goodwi	Benicia, CA 945101097
Inoperable monitors as defined by BAAQMD Regulations 1-522 and 1-523 for the reporting period are summarized below	Fuel Opacity/ Wind Wind Guage W CEM GLM Gas Parametric NOx SO2 CO H2S TRS NH3 O2 CO2 H2O LTA Lead Steam Flow Dir. Speed pH Temp. VOC Press.
Ref: 1294 Event Started: <u>12/31/2023 4:00 PM</u> Stopped: <u>1/14/2024 6:30 AM</u> ✓ Has Stopped	
Source Number: S1030-Combustion Turbine Generator, GT-4901; S1031-Heat Recovery Steam Generator, SG-4901	
	Amendment 1/16/24: Internal parts were replaced and the analyzer was calibrated and brought back online. Cogen H2S/TRS CEMS analyzer stopped reading at 4:00 pm on 12/31/23. The analyzer became inoperative for greater than 24 hours on 1/1/2024 at 4:00 pm. Internal parts are being ordered for repairs.
Abatement Device: Emission Point:	1/1/2024 at 4.00 pm. Internal parts are being ordered for repairs.
Ref: 1299 Event Started: 1/15/2024 6:00 AM Stopped: 1/19/2024 3:04 PM Has Stopped	
Source Number: S1030-Combustion Turbine Generator, GT-4901; S1031-Heat Recovery Steam Generator, SG-4901	Event Description: Amendment 1/24/2024: On 1/15/2024 6:30 AM the Cogen mercaptans analyzer failed calibration. Analyzer became inoperative >24hrs on 1/16/2024 at 6:31 AM. Analyzer was re-calibrated and passed 1/19/2024 3:04 pm. The Inop is being reported beyond the following business day after a period of inoperation greater than 24 continuous hours. On 1/15/2024 6:30 AM the Cogen mercaptans analyzer failed calibration. Analyzer became inoperative >24hrs on 1/16/2024 at 6:31 AM.
Abatement Device: Emission Point:	Analyzer was re-calibrated and passed 1/19/2024 3:04 pm

Wednesday, July 24, 2024 Page 1 of 3

From 1/1/2024 to 6/30/2024

B2626 Vale	o Benicia Refinery
Facility Address: 3400 East Secon Benicia, CA 945	
Contact: Taryr	Goodwin Title: Manager - Environmental Engineering Phone: (707) 745-7475
noperable monitors as defined by BAAQMD Regulations 1-522 and 1-523 for the reporting period are summari.	Fuel Opacity/ Wind Wind Guage Guage CEM GLM Gas Parametric NOx SO2 CO H2S TRS NH3 O2 CO2 H2O LTA Lead Steam Flow Dir. Speed pH Temp. VOC Press.
Ref: 1300 Event Started: 1/25/2024 5:39 AM Stopped: 1/26/2024 5:55 PM 🗹 Has St	opped
Source Number: S7-Process Furnace, Jet Fuel Hydrofining, F-103; S20-Process Furnace, Naphtha Hydrofining, F-104; S30-Process Furnace, PFR Preheat, F-2901; S31-Process Furnace Preheat, F-2902; S32-Process Furnace, PFR Preheat, F-2903; S33-Process Furnace, Preheat, F-2904; S34-Process Furnace, Gas Heater, F-2905; S35-Process Furnace, Heater, F-2906; S21-Hydrogen Reformer Furnace, F-301; S22-Hydrogen Reformer Furnace, F-301; S22-Hydrogen Reformer Furnace, F-351; S23-Gas Oil Hydrocracking, F-401; S220-Hot Oil Furnace, F-4460; Process Furnace, Cat Feed Hydrofining, F-601; S25-Process Furnace, Cat Feed Pre 701; S26-Process Furnace, HCN Hydrofining, F-801; S173-Coker Steam Superheat Furnace, F-902; S1030-Combustion Turbine Generator, GT-4901; S238-Pre-BIOX of for Stripped Sour Water; S237-Boiler, SG-1032; S40-Steam Generator, SG-2301; S1031-Heat Recovery Steam Generator, SG-4901; S248-Reactor Charge Heater, ULSD Unit, F-5401; S248-Stripper Reboiler Heater, ULSD S402 Abatement Device: Emission Point:	, PFR Gas
Ref: 1324 Event Started: 4/9/2024 1:35 AM Stopped: 4/10/2024 2:40 PM ✓ Has St	opped
Source Number: S30-Process Furnace, PFR Preheat, F-2901; S31-Process Furnace, PFR Preheat, F-2903; S33-Process Furnace, PFR Preheat, PF	
Ref: 1327 Event Started: 5/5/2024 7:13 AM Stopped: 5/6/2024 1:00 PM 🗹 Has St	opped 💌 🗆 💮 🐷 🗆 🗆 🗆 🗆 🗆 🗆 🗆 🗆 🗆 🗆 🗆 🗆 🗆
Source Number: S21-Hydrogen Reformer Furnace, F-301 Abatement Device: Emission Point:	Event Description: The F-301 NOx and O2 analyzer became inoperative for greater than 24 hours on 5/5/2024 at 07:13. The analyzer was returned to service on 5/6/2024 at 13:00.

Wednesday, July 24, 2024

From 1/1/2024 to 6/30/2024

B2626 Valero Beni	icia Refi	nery	•																		
Facility Address: 3400 East Second Street Benicia, CA 945101097								3400	Address East Sec a, CA 9	ond S											
Contact: Taryn Goodw	in			Tit	le: Mana	ger - Ei	nvironn	nental	Engine	ering		Phone	: (707)	745-74	175						
Inoperable monitors as defined by BAAQMD Regulations 1-522 and 1-523 for the reporting period are summarized below	CEM G		Fuel Gas	Parametric	NOx S	D2 C	O H2	S TR	S NH3	02	CO2	H2O	Opacity LTA		Steam	Flow	Wind Dir.		pH Ten	np. VO	Guage C Press.
Ref: 1328 Event Started: <u>5/15/2024</u> 1:55 PM Stopped: <u>5/28/2024</u> 4:17 PM ✓ Has Stopped			•				•	•													
Source Number:	Event De	escript		mendment nd was turr						ve for >	>24 ho	urs 5/15	5/2024 1	:55 PM	. The an	alyzer w	as repa	red, had	d a passir	ıg valida	ation
Abatement Device: Emission Point:			Fu	uel gas H2S	and TRS b	ecame	inopera	ive for	>24 hou	ırs 5/1!	5/2024	1:55 PI	M.								
Ref: 1329 Event Started: <u>5/25/2024</u> 3:10 PM Stopped: <u>5/28/2024</u> 10:34 AM ☑ Has Stopped				•																	
Source Number: S19-North Flare, ST-2103	Event De	escript	2ª ar	he North Fl 4 hours on nd the cont me was not	5/25/24 at rol house v	3:10 P vas res	M due a tored ar	comm d the i	unicatio	n loss b ed on !	oetwee 5/28/2	n the a 4 at 10:	nalyzer a 34 am.	ind the Γhere w	control as no fl	house. aring du	Commu	nication	betwee	n the an	nalyzer
Abatement Device: Emission Point: P3-North Flare Emission Point, P-3																					
Certification Statement I certify under penalty of law that based on the information and belief formed after reasonable inquiry, the statements and information in this document and in all attachments and other materials are true, accurate, and complete. X Hawry K. Buy Lauren Bird Vice President and	d General	Mana	ager																		
Signature of Responsible Official Print Name Title	a Scholar	viuit	-601		Date																

From 1/1/2024 to 6/30/2024

A0901

Valero Benicia Asphalt Plant

Facility Address:

3001 Park Road Benicia, CA 94510

Contact: Taryn Goodwin

Mailing Address:

3001 Park Road Benicia, CA 94510

Title: Manager - Environmental Engineering

Phone: (707) 745-7475

Inoperable monitors as defined by BAAQMD Regulations 1-522 and 1-523 for the reporting period are summarized below

No Inoperable Monitors for this time period.

Certification Statement

I certify under penalty of law that based on the information and belief formed after reasonable inquiry, the statements and information in this document and in all attachments and other materials are true, accurate, and complete.

Lauren Bird

Vice President and General Manager

Signature of Responsible Official

Print Name

Title

Date

Wednesday, July 24, 2024

From 1/1/2024 to 6/30/2024

B5574 **Nustar Logistics**

Facility Address:

3400 East Second Street Benicia, CA 94510

Contact: Taryn Goodwin

Mailing Address:

3400 East Second Street Benicia, CA 945101097

Title: Manager - Environmental Engineering

Phone: (707) 745-7475

Inoperable monitors as defined by BAAQMD Regulations 1-522 and 1-523 for the reporting period are summarized below

No Inoperable Monitors for this time period.

Certification Statement

I certify under penalty of law that based on the information and belief formed after reasonable inquiry, the statements and information in this document and in all attachments and other materials are true, accurate, and complete.

Lauren Bird

Vice President and General Manager

Print Name

Title

Date

Wednesday, July 24, 2024