## BAAQMD Title V Permit 6 Month Monitoring Report

From 1/1/2013 to 6/30/2013

				J		
	A0011 Shell Oil Products t	Shell Oil Products US Martinez Refinery				
	Facility_Address: 3485_Pacheco_Bivd		Mailing Address PO Box Z11			
	City: Martinez State: CA Zip Code: 94553-0071		City: Martinez State: CA Zip Code: 94553-0071			
	Contact: Liz Rosales		Tītle: Environmental Speciali. Phone: (925) 313-3857_			
Inoperable monitors as defined by BAAQMD Regulations 1-522 and 1-523 for the reparting period are summarized below:	522 and 1-523 for the reporting period are s	ummarized below:		Į		
Started Stopped	Source (S#)  Abatement Emission Device (A#) Point (P#)	on Fuel '#) CEM GLM Gas Parametri NOx SO2	Opacity/ Iri NOx SO2 CO H2S TRS NH3 O2 CO2 H2O LTA Lead Steam Flow Wind Dir, Speed pH Temp. VOC. Press	Wind r. Speed pH T	emp, VOC.	Gauge
1/26/2013 5:05 PM 1/29/2013 12:00 PM 🛜 4193 A4192  Event Description: Cogen 2 NOx analyzer 66A1617 out of service during replacement with a new analyzer. RATA performed by Shell. Downtime occurred until Air Di	4193 A4192 turing replacement with a new analyzer. RATA po	☑ ☐ ☐ ☐	© □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □	0	_ _	
2/16/2013 4:55 AM 2/18/2013 9:30 AM 🕢 1435  Event Description: 9A1610, Refiney Fuel Gas H2S analyzer, failed calibration and was out of service over 24 hours. The analyzer was returned to service after adjusting fuel burn ratios	1435 calibration and was out of service over 24 hours.	☐ ☐ ☐ ☐	after adjusting fuel burn ratios.			
2724/2013 4:55 AM 2725/2013 10:00 AM 🕝 Event Description: 9A11610 H2S analyzer on Refinery Fuel Gas failed verification due to low voltage issues and was out of service over 24 hours. Adjustments were made and analyzer was placed back into service	led verification due to low voltage issues and was	out of service over 24 hours. Adjus	□□□ S3 □□□□□□□□□□□□□□□□□□□□□□□□□□□□□□□□			
3/3/2013 6:30 AM 3/4/2013 2:55 PM G  Event Description: NOx and O2 Analyzers 2A2727 and 2A2728 on Chimney I West Breach were out of service due to O2 cell failure.	P-23 Chimney I West Breach were out of service due t	Ø □ □ □				
4/1/2013 9:00 AM 4/4/2013 10:25 AM	l out of service for annual rebuild as part of its pro	ventutive maintenance.	8 000000			
4/15/2013 10:25 AM 4/18/2013 9:25 PM 52  Event Description: Refinery Fuel Gas H2S analyzer 9A11610 to LOP was taken out of service for an annual rebuild.	P was taken out of service for an annual rebuild.	<b>&amp;</b>	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0			
6/30/2013 2:23 AM 7/1/2013 10:37 AM	1511 greater than 24 hours due to loss of communication	with the data archive software prop		0		