BAAQMD Title V Permit 6 Month Monitoring Report

From 1/1/2012 to 6/30/2012

	N					8
	Zip Code: 94553-007	Sa	Ω		ZZZ	A0011
	Б	State: CA	City: Martinez	ψ	Eacility Address:	
	1553	٥	artino	3485 Pacheco Blvd	Addre	Sh
	8671		22	ache	335	<u>e</u>
Q				С		<u>=</u>
Contact: Liz Rosales				å.		ŏ
#						튭
iž Ro						S
sales						_S
				i		引
						200
						Shell Oil Products US Martinez Refinery
层。						ğ
E S						ž
iron						
ent	2					
Title: Environmental Special	S e	Sta	_		Mailli	
eciali	de: s	ĭe: (3	_	A DI	
	¥55;	State: CA	City: Martinez	ŏ	Mailing Address	
윩	Zip Code: 94553-0071		ğ	PO Box 711	Kń	
Phone: (925) 313-3857	7			7		
(92						
5) 31				60		
3-38						
157						
7.000						
100				400,000	e76566	

Event Description: Event Description: The RFG BTU parametric analyzer 9A2719 is out of service greater than 24 hours due to a transmitter problem that is currently being worked with the factory. Other preventative maintenance items are being performed during this downtime. Event Description: Event Description: COB #1 CO analyzer 9A2640 was out of service due to sample tube plugging. System was flushed and recalibrated. Started Event Description: Event Description: Event Description: 1/10/2012 7:15 AM Inoperable monitors as defined by BAAQMD Regulo 2/20/2012 11:00 AM 2/20/2012 11:00 AM 1/16/2012 10:00 AM 1/10/2012 7:15 AM 3/5/2012 10:30 AM 1/6/2012 9:00 AM 3/5/2012 10:30 AM AM 3/17/2012 12:10 PM (2) (2) RFG to Clean Fuels H2S analyzer # 9A2831 will be out of service for several days as it goes through it's annual rebuild as preventative maintenance. Ace Hardware SQ2 GEM 1A1472 was out of service greater than 24 hours. Technicians trouble shot & replaced mirrors, intensity board, flasher lamp socket andf flasher lamp. Cogen #2 O2 analyzer is out of service for greater than 24 hours. There is an issue with the sample system. The issues are currently being worked. COB #2 CO analyzer 9A2642 was out of service greater than 24 hours due to sample tube plagging. System was flushed and recalibrated COB #2 Opacity analyzer 09A2531 "chart recorder" jammed and stopped recording greater than 24 hours. All data captured through Raddical. RFG To Clean Fuels TRS analyzer # 9A2825 will be out of service for several days as it goes through it's annual rebuild as preventative maintenance Cogen #2 NOx analyzer 66A616 is out of service greater than 24 hours. There is an issue with the sample system. The issues are being worked 1/11/2012 4:04 PM 3/19/2012 9:00 AM 2/21/2012 3:15 PM 2/2/2012 3/17/2012 12:10 PM 2/21/2012 3:15 PM 1/11/2012 7:00 AM 9:15 AM 4:06 PM 8 3 (3) S S 3 4193 1507 1/1/472 4193 1509 Source (S#) A4192 >:2 Abatement Device (All) **>13** 213 Emission Point (P#) CEM GLM Gas Parametri S \square 3 3 3 (3 < NOx SO2 CO H2S S (3) 5 S ____ TRS NH3 O2 CO2 H2Q LTA 3 G \Box ____ \$ Lead Steam Flow Wind Dir, Speed pH \Box $\begin{bmatrix} 1 \end{bmatrix}$ \Box (_ \Box _ \Box 0 Temp. VOC \Box \Box \square ____ _ Gauge Press

Frulay, July 06, 2012

Abatement Emission	Fuel Opacity/ Wind Gauge
Started Source (SE) Device (AE) Point (PE)	Parametri NOx SO2 CO H2S TRS NH3 O2 CO2H2O LTA Lead Steam Flow Wind Dir. Speed p.H. Temp. YOC.
4/16/2012 2:20 PM 4/25/2012 2:10 PM 😴	
Event Description: RFG H2S analyzer 9A1610 is out of service greater than 24 hours. It will be out of service for several days due to the annual rebuild, warm-up, and calibration.	ays due to the annual rebuild, warm-up, and calibration.
4/29/2012 5:00 AM 4/30/2012 7:45 AM	
Eyent Description: RFG H2SS analyzer 9A 1610 failed calibration verification at the action finit. Technician adjusted flows, pressure and verified calibration prior to returning the analyzer to service.	s, pressure and verified calibration prior to returning the analyzer to service.
5/12/2012 3:32 AM 5/14/2012 9:00 AM 😅 1510	
Event Description: NOx and O2 CEMS (5A2856 and 5A2857) on F-66 manifunctioned due to plugging in the sample line.	
5/14/2012 8:00 AM 5/16/2012 2:40 PM 😾 1426	
Event Description: 9A2293 FCCU O2 analyzer is inoperative and awaiting factory parts for repair.	
6/2/2012 6:10 AM 6/4/2012 10:90 AM 🕝 1759 A751	
Event Description: Flexigas H2S analyzer 14 A 1251 out of service due to sample valve plugging during auto calibration.	
6/12/2012 8:00 AM 6/13/2012 3:20 PM	
Event Description: IfP1 parametric analyzer 10A1024, CH4 start up & shut down post-methanator vent is out of control for greater than 24 hours. Analyzer failed calibration and was down for repairs.	greater than 24 hours. Analyzer failed calibration and was down for repairs.
6/18/2012 10:40 AM 6/20/2012 3:50 PM 😥	
Event Description: SRU #4 TRS analyzer 18A0234 will be out of service for greater than 24 hours for its annual rebuild and preventative maintenance.	d preventative maintenance.

Certification Statement

attachments and other materials are true, accurate, and complete.	reasonable inquiry, the statements and information in this document and in all	I certify under penalty of law that based on the information and belief formed after	
---	--	--	--

x 10 Hold out Signature of Responsible Official

Paul (Tobberd (Jopennal Manager 7/10/12
Print Name Title