

## Minor corrections to final Title V permit for EBMUD

1. Table IV-F, S54, Diesel Engine BUG:
  - a. The citation of the Ringelmann 2 limit in BAAQMD Regulation 6, Rule 1, Particulate Matter – General Requirements, has been corrected from 6-1-301 to 6-1-303.
  
2. Condition 24050 for S56, Digester Gas Turbine, part 7: Since it has been determined that the turbine is subject to 40 CFR 60, Subpart KKKK, not 40 CFR 60, Subpart GG, the citation of 40 CFR 60.335 has been changed to 40 CFR 60.4400. Since Subpart KKKK does not require testing at multiple loads, this language has been deleted. The word “initial” has been deleted because initial compliance has been demonstrated.

“To demonstrate ~~initial~~ compliance with parts 3, 4, and 5, above, the owner or operator shall annually thereafter perform a District-approved compliance source test ~~at multiple loads~~ as specified in 40 CFR 60.~~4400335~~, as applicable. The sample port design and locations shall be approved by the District Source Test Section prior to installation. The annual test shall be performed at a frequency of no sooner than 9 months and no later than 12 months after the previous source test.
  
3. Glossary: A definition of BUG (back-up generator) has been added to the glossary.