

Thu Bui

From: Brandes, Rich [Rich.Brandes@kaneb.com]

Sent: Thursday, June 02, 2005 3:49 PM

To: Thu Bui

Subject: Application #10492; Minor Revision to Major Facility Review Permit for Shore Terminals Martinez

Thank you for the opportunity to review the proposed revision. I have provided several comments below:

1. Please modify the District records regarding the responsible official for the Martinez, Selby and Richmond Terminals. The following Shore Terminals names should be deleted from the permit cover page: Michael J. Burgett / Myles Butler. These individuals are no longer with the company.

Responsible Official: Richard W. Brandes, Manager of Environmental and Regulatory Oversight
Facility Contact: Michael J. Peterson, General Manager - Southwest

I know you didn't attempt to correct the following in this version, but I'll list them for your later changes.

2. Permit Page 8. A-1 is used as the correct designation of the thermal oxidizer unit. A-41 is incorrectly used later in the permit(see below).

3. Permit Page 77. In paragraph IV, the marine vessel loading abatement unit is referred to as A-41. This should be A-1.

4. Permit Page 78. Paragraph 7, second paragraph. A-41 should be A-1

Regards,

Richard Brandes

Manager, Environment and Regulatory Oversight

Kaneb Terminals / Shore Terminals / ST Services

925-228-3227 ext 120

925-228-5617 (fax)

7/14/2005